Janine Derlin Zenith Explorer

4	5	6	7

Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice

Panama 9464534 1-May Drydock in Fuzhou

8	ξ	10
Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption
Vancouver,bc	Fuzhou	Fuzhou

11 12 13

Name of Original Fuel Supplier with Disruption Number of Fuel Suppliers Contacted Date of Entry in the ECA

Sinopec Fuzhou:

No.47 Guping Road, Gulou district, Fuzhou

City Fujian Province, China

Tel: +86 591 88508524

Pic: miss chen

Mobil: +86 15980288962

Email: chenly.fuel@sinopec.com 1 19-May

14	15	16
14	10	10

Time of Entry in the ECA Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion

11:00 3.00% 3.5 days

17	•	18	19
Name of First POC	Compliance Fuel Oil Available at First POC	? Plan to Bunker Compliant Fuel Oil at First F	POC?
Vancouver,Bc	yes	yes	

20 21 22

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC?

2+ - -

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC?

no nil

2	5	26

27

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months?

26-May

19:00 no

28	3 2	29	30
Number of Separate Visits to the ECA	Number of Ports visited in the ECA	A Previously submitted ECA0100 form	ıs?

\_ \_

31		32	33
Number of Submitted Reports	Designated Corporate Officia	l Name Designated	Corporate Official E-mail

- pls advise pls advise

34 35

Designated Corporate Official Phone Number Description of Actions to Achieve Compliance

pls advise

vsl will be supplied with lsf in vancouver,bc